

**WELL & PIPELINE ABANDONING FLUID****ABANDONING A WELL?**

Abandoning fluid is added to control corrosion and to eliminate oxygen which aids in the corrosion process.

ABANDONRITE "W"		A highly concentrated "weighted" water soluble abandonment fluid containing corrosion inhibitor and oxygen scavenger additive used as an aid in preventing corrosion  <b>NOTE: For more information see Technical Data Sheet</b>
PART NO.	SIZE	
ACL-ABW-20	20 LITRE PAIL	
ACL-ABW-205	205 LITRE DRUM	
ACL-ABW-1025	1025 LITRE TOTE	